

Warning

Clothing with metallic microfibers should not be worn in the MRI machine as the fibers **could burn the skin.**

Alert an Akumin staff member, if you are wearing any article of clothing that could potentially have metallic microfibers.

These fibers are often found in **exercise, spandex and stretch attire.** For your safety, we will provide you with a cloth gown to wear during your exam.

